MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SECTION CORNER RECORD SEC. $6\,\mathrm{TWN}$. $15_{\mathrm{N}}\,\mathrm{RNG}$. 3_{E}

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

Date: 7-20-09

Party Chief: Wilcoxen//Greene


Crew: Finney


Type of Marker: PK nail fd at surface

Method of Establishment: County: 1-17-1995

Name: 15030617







4.

| REF. | DISTANCE | DESCRIPTION |
|------|----------|--|
| 1. | 16.75' | Mag nail w/brass washer SE PwP #12-496 B 8" up |
| 2. | 125.27' | Mag nail S PwP # 15-496 B 15" up |
| 3. | 953.06' | Due E to Center 6-15-3 (stone) |
| 4. | 65.20' | NW concrete porch slab 5005 Vermont St |
| 5. | 105.44' | Road nail N PwP #11-496 B 12" up |
| 6. | 35.45' | Mag nail w/brass washer W PwP#13-496 B 20" up |
| | | |
| | | |
| | | |

REFERENCE

Tie sheet from 1-12-83: The corner was dug in the fall of 1982. Found stone per Wayne Township Legal Book pg 94. (ID'ed as "c" on said survey) MCSO Job #820098

THIS CORNER POSITION
REPRESENTS A "TITLE" CORNER
AND MAY NOT NECESSARILY
REPRESENT THE POSITION BASED
ON RECORD CORNERS.